

From: Jan Morse
To: Paul Baker
Date: 10/1/2007 6:46 PM
Subject: Daneros Comments S0370121

Paul,

Here are my comments from my review of the Daneros NOI.

1. The operating plan submitted to BLM is weak in the monitoring section. It should contain more information about monitoring equipment, frequency, adverse monitoring result thresholds and procedures. Maybe we can get some standards from MSHA.

For solid materials, we would want some background radiation measurements before the waste and ore stockpiles are begun, and then we would know what to reclaim to at the end.

For water quality, a silt fence and berm seems a little weak for protecting the water source. Again, we would need some background radiation measurements. I think AMR has some water-quality data from Cottonwood Wash. It may help us get an idea of what exists in the area.

2. Map does not show location of proposed second adit.

3. Information about the water body inside the mine is unclear and confusing. Can it be mapped?

AMR-
Sub on
Waste rock